

FIG. 1




FIG. 2




FIG. 3




FIG. 4a




FIG. 4b

1006338.070300





FIG. 5

Chart: Grain Size (diameter)
Edge grains excluded from analysis



Average
Number
Area

63.9569
116.019


Grain Size distribution and data - Sample Ta A 1050

FIG. 6



20E040.8E9E00T

Chart: Grain Size (diameter)
Edge grains excluded from analysis




Grain Size distribution and data - Sample Ta U 1100

FIG. 7



Chart: Grain Size (diameter)

Edge grains excluded from analysis




Average
Number 16.878
Area 26.9294

Grain Size distribution and data - Sample Nb A 1250

FIG. 8



Chart: Grain Size (diameter)
Edge grains excluded from analysis



Average
Number 9.59034
Area 15.3075

Grain Size distribution and data - Sample Nb u 1100

FIG. 9

